



Galloway Dam Spillway Restoration, Monroe Creek (Weiser River CD)

Program	Water Quality Implementation
Lead Implementer	Weiser River Conservation District
Funders	Idaho Department of Environmental Quality, Idaho Soil and Water Conservation Commission, Weiser River Conservation District
Project Primary Contact	Bill Lillibridge (bill.lillibridge@swc.idaho.gov)
Project Stage	Implementation
Duration	2020 - 2021

Natural Resource Projects & Practices ➤ Water Quality Implementation

The cement spillway is over 100 years old and degraded significantly. Large areas of cement are eroding causing streambank erosion, safety issues and water quality issues from excess sediment.

No Key Photo provided


Key Accomplishments

- Engineering Designs Produced: 5
- Permits Prepared & Submitted: 5
- Engineering & Technical Assistance Hours Requested: 116
- Engineering & Technical Assistance Hours Allocated: 116
- Engineering & Technical Assistance Hours Provided: 226
- Engineering & Technical Assistance Value: \$17,006.50

Project Themes

- Water

Location



Expenditures

No expenditures provided

Photos

No additional photos provided

Tracker tells stories at a broad-brush level. Individual project performance measures and expenditures should not be relied upon for complete and total accuracy and should be confirmed with a project's lead implementer. Project locations subject to confidentiality provisions under state and federal law specify the location of a local conservation district or USDA service center office.

Project last updated 4/9/2021